

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2017

Submitted Date:

10/14/2017

Document Number:

688300472**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 451622      Sherman, Susan      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON      State: TX      Zip: 77252-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strickler, Robert		Robert.D.Strickler@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	<a href="#">All DJ Basin Inspections</a>
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	<a href="#">Regulatory Supervisor</a>
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	<a href="#">Regulatory Coordinator</a>
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	<a href="#">Production</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451919	WELL	XX	08/28/2017		005-07327	State Challenger 5-65 2-3 3BYH	DG

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	location signs		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	Sings at Watkins Rd and access road turnoff		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flare	# 1		
Comment:	Emergency flare on NE corner of location		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

### Location Construction

Location ID: 451919 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No problems seen on location. Two driveways, an entrance and an exit.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 451919 Type: WELL API Number: 005-07327 Status: XX Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: H&P 448 Pusher/Rig Manager: Richard Perez  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 3500 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: NO Unlined Pit: NO Closed Loop: YES Semi-Closed Loop: NO  
 Multi-Well: NO Disposal Location: Commercial

**Comment:** Surface TD 2307', 13 3/8" surface casing, 17 1/2" hole, conductor pipe set

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Cement****Cement Contractor**

Contractor Name: Halliburton Contractor Phone: \_\_\_\_\_

**Surface Casing**

Cement Volume (sx): 1120 Circulate to Surface: YES  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

**Intermediate Casing**

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Production Casing**

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

**Plugging Operations**

Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): \_\_\_\_\_  
 Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

**Comment:** Swiftcem. Perfect hole.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: [State land, pasture](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Rip Rap	Pass			
Gravel	Pass	Gravel	Pass	Spill Response	Pass	
Seeding	Pass	Seeding	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass	Ditches	Pass			
Culverts	Pass	Culverts	Pass			
Check Dams	Pass	Check Dams	Pass	Covering Materials	Pass	
Tackifiers	Pass	Tackifiers	Pass			
Waddles	Pass	Waddles	Pass	Self Inspection	Pass	
Retention Ponds	Pass	Blankets	Pass			

Comment: [Liner under rig and tanks. Excellent site.](#)

Corrective Action:

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300476	Conoco State Challenger 5-65 2-3 3BYH	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274546">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274546</a>