

Inspection Photos

10/13/2017

Operator: STELBAR OIL CORP INC - 82470

Location ID: 317155

Inspection Doc. Number: 682502708

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: STELBAR OIL CORP INC - 82470
Location ID: 317155



Photo 1: Photo taken from the south end of the location, facing west. Photo shows the reclamation area. Reclamation area is predominantly exposed soil, and does not appear to be progressing towards COGCC 1000 series reclamation standards and requirements.



Photo 2: Photo taken from the south end of the location, facing northwest. See comments under photo 1.

Inspection Photos
Operator: STELBAR OIL CORP INC - 82470
Location ID: 317155



Photo 3: Photo taken from the south end of the location, facing northeast. See comments under photo 1.



Photo 4: Photo taken from the south end of the location, facing east. See comments under photo 1.



Photo 5: Photo taken from the location. Photo shows vegetation over the reclamation area predominantly undesirable weedy plant species such as *Tribulus terrestris*.



Photo 6: Photo taken from the location. Inspector had tested the site for compaction concerns. Photo shows inspector was only able to penetrate the first couple of inches of topsoil with relative ease.



Photo 7: Photo taken from the reference area. Inspector had tested the soil in the reference area for comparison to that of the disturbance area. Photo shows inspector was able to easily penetrate the topsoil.



Photo 8: Photo shows vegetation over the adjacent reference area.