

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2017

Submitted Date:

10/17/2017

Document Number:

666803865**FIELD INSPECTION FORM**

Loc ID 311651	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 13 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																											
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Knudson, Dwayne</td> <td>970-456-3335</td> <td>dknudson@ursaresources.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>					Contact Name	Phone	Email	Comment	Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>																																																																															
Contact Name	Phone	Email	Comment																																																																																								
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>																																																																																								
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>283411</td><td>WELL</td><td>PR</td><td>10/25/2006</td><td>GW</td><td>045-11917</td><td>SNYDER A 1</td><td>PR</td></tr> <tr><td>285152</td><td>WELL</td><td>PR</td><td>06/05/2007</td><td>GW</td><td>045-12398</td><td>SNYDER A10</td><td>PR</td></tr> <tr><td>285153</td><td>WELL</td><td>PR</td><td>10/13/2011</td><td>GW</td><td>045-12397</td><td>SNYDER A3</td><td>PR</td></tr> <tr><td>285154</td><td>WELL</td><td>PR</td><td>06/05/2007</td><td>GW</td><td>045-12396</td><td>SNYDER A4</td><td>PR</td></tr> <tr><td>285155</td><td>WELL</td><td>PR</td><td>12/11/2007</td><td>GW</td><td>045-12395</td><td>SNYDER A5</td><td>PR</td></tr> <tr><td>285156</td><td>WELL</td><td>PR</td><td>10/01/2012</td><td>GW</td><td>045-12394</td><td>SNYDER A9</td><td>PR</td></tr> <tr><td>289761</td><td>WELL</td><td>PR</td><td>11/04/2011</td><td>GW</td><td>045-13872</td><td>SNYDER A7</td><td>PR</td></tr> <tr><td>290978</td><td>WELL</td><td>PR</td><td>03/30/2012</td><td>GW</td><td>045-14241</td><td>SNYDER A11</td><td>PR</td></tr> <tr><td>292324</td><td>WELL</td><td>PR</td><td>09/19/2007</td><td>GW</td><td>045-14678</td><td>SNYDER A13</td><td>PR</td></tr> <tr><td>292325</td><td>WELL</td><td>PR</td><td>09/19/2007</td><td>GW</td><td>045-14677</td><td>SNYDER A12</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	283411	WELL	PR	10/25/2006	GW	045-11917	SNYDER A 1	PR	285152	WELL	PR	06/05/2007	GW	045-12398	SNYDER A10	PR	285153	WELL	PR	10/13/2011	GW	045-12397	SNYDER A3	PR	285154	WELL	PR	06/05/2007	GW	045-12396	SNYDER A4	PR	285155	WELL	PR	12/11/2007	GW	045-12395	SNYDER A5	PR	285156	WELL	PR	10/01/2012	GW	045-12394	SNYDER A9	PR	289761	WELL	PR	11/04/2011	GW	045-13872	SNYDER A7	PR	290978	WELL	PR	03/30/2012	GW	045-14241	SNYDER A11	PR	292324	WELL	PR	09/19/2007	GW	045-14678	SNYDER A13	PR	292325	WELL	PR	09/19/2007	GW	045-14677	SNYDER A12	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																				
283411	WELL	PR	10/25/2006	GW	045-11917	SNYDER A 1	PR																																																																																				
285152	WELL	PR	06/05/2007	GW	045-12398	SNYDER A10	PR																																																																																				
285153	WELL	PR	10/13/2011	GW	045-12397	SNYDER A3	PR																																																																																				
285154	WELL	PR	06/05/2007	GW	045-12396	SNYDER A4	PR																																																																																				
285155	WELL	PR	12/11/2007	GW	045-12395	SNYDER A5	PR																																																																																				
285156	WELL	PR	10/01/2012	GW	045-12394	SNYDER A9	PR																																																																																				
289761	WELL	PR	11/04/2011	GW	045-13872	SNYDER A7	PR																																																																																				
290978	WELL	PR	03/30/2012	GW	045-14241	SNYDER A11	PR																																																																																				
292324	WELL	PR	09/19/2007	GW	045-14678	SNYDER A13	PR																																																																																				
292325	WELL	PR	09/19/2007	GW	045-14677	SNYDER A12	PR																																																																																				

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283411	WELL	PR	10/25/2006	GW	045-11917	SNYDER A 1	PR
285152	WELL	PR	06/05/2007	GW	045-12398	SNYDER A10	PR
285153	WELL	PR	10/13/2011	GW	045-12397	SNYDER A3	PR
285154	WELL	PR	06/05/2007	GW	045-12396	SNYDER A4	PR
285155	WELL	PR	12/11/2007	GW	045-12395	SNYDER A5	PR
285156	WELL	PR	10/01/2012	GW	045-12394	SNYDER A9	PR
289761	WELL	PR	11/04/2011	GW	045-13872	SNYDER A7	PR
290978	WELL	PR	03/30/2012	GW	045-14241	SNYDER A11	PR
292324	WELL	PR	09/19/2007	GW	045-14678	SNYDER A13	PR
292325	WELL	PR	09/19/2007	GW	045-14677	SNYDER A12	PR

<b>General Comment:</b>
-------------------------

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: Flow line

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift # 10

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Pig Station # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 12

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents # Capacity Type Tank ID SE GPS

PRODUCED WATER 3 300 BBLs STEEL AST

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		39.532215,-107.733763
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	283411	Type:	WELL	API Number:	045-11917	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285152	Type:	WELL	API Number:	045-12398	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285153	Type:	WELL	API Number:	045-12397	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285154	Type:	WELL	API Number:	045-12396	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285155	Type:	WELL	API Number:	045-12395	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	285156	Type:	WELL	API Number:	045-12394	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289761	Type:	WELL	API Number:	045-13872	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290978	Type:	WELL	API Number:	045-14241	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	292324	Type:	WELL	API Number:	045-14678	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	292325	Type:	WELL	API Number:	045-14677	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803877	ursa	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4277161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4277161</a>