

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401388378  
Date Received:  
09/22/2017

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Adamczyk, Megan</u>		<u>megan.adamczyk@state.co.us</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303650  
Inspection Date: 08/04/2017 FIR Submit Date: 08/10/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326263

Location Name: ANNALA FEDERAL GAS UNIT Number: 15NENW County: LA PLATA  
A-M34N8W  
Qtrqtr: NENW Sec: 15 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.219660 Longitude: -107.733410

FACILITY - API Number: 05-067-00 Facility ID: 216135

Facility Name: ANNALA FEDERAL A Number: 1  
Qtrqtr: NENW Sec: 15 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.219660 Longitude: -107.733410

CORRECTIVE ACTIIONS:

1  CA# 91006

Corrective Action: Install or repair berms or other secondary containment device to comply with Rule 605.a.(4).

Date: 09/10/2017

Response: CA COMPLETED

Date of Completion: 08/18/2017

Operator Comment: Weeds on this location and within the containment have been manually removed followed up by treatment with herbicides to prevent regrowth. See attached documentation of work completed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

2  CA# 91007

Corrective Action: Confirm natural gas motor is equipped with quiet design muffler or equivalent and muffler is properly installed and maintained in working order per Rule 802.f.

Date: 08/26/2017

Response: CA COMPLETED

Date of Completion: 07/31/2017

Operator Comment: In July a landowner complaint was received regarding the noise on this location. The Operations personnel then made necessary repairs to this muffler and hoses. Operations has returned to location on the 21st of August and has confirmed that the correct muffler is installed and all components are functioning properly. The muffler installed on this C 66 engine is a Arrow MUF-1-H muffler which is hospital grade muffler with a 30 - 35 db noise reduction rating. In reviewing the installation/owners manual there is no specifications for Service & Maintenance schedules for the muffler. In addition contact was made with Arrow Engine Co who states "The only thing I can say is Arrow does not put an expected life span on any of its mufflers or silencers due to varying applications, fuels, environment and load conditions." per Roger Dennison of Arrow Engine Co. See attached documents

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

3  CA# 91008

Corrective Action: Remove, chip and spread, or burn with landowner permission to comply with Rule 1003.a.

Date: 09/10/2017

Response: CA COMPLETED

Date of Completion: 08/18/2017

Operator Comment: Debris from wood cutting has been removed from location and disposed of please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

4  CA# 91009

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 09/10/2017

Response: CA COMPLETED

Date of Completion: 09/20/2017

Operator Comment: Wattles have been installed in erosion channel to control the velocity of storm water flow and rilling see attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has addressed the CA regarding the noise complaint, weeds and wood debris on location. See attached documents regarding the muffler.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: \_\_\_\_\_

Title: Compliance Specialist Date: 9/22/2017 2:18:21 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401388378	FIR RESOLUTION SUBMITTED
401388381	Photos of work completed
401411538	Arrow muffler documentation

Total Attach: 3 Files