

Location			
Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by gate at entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 415668 Type: WELL API Number: 125-11742 Status: DG Insp. Status: DG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA at time of inspection. Passing MIT performed on 3/6/17. Form 21 #401227766 is In Process at time of inspection

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: [Location is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT