

Inspection Photos
Well Name: Nichols 18-24 Follow Up
Location ID: 312659



Photo 1. Follow up to inspection Doc#689400114 in response to FIRR Doc#401428489. Capacity has been added to tank. Form 4 has been filed for continued TA status.