

Construction and Stormwater Inspection

October 12, 2017

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC -#8960

Location ID: 450205

Weld County, CO

SESE Section 22 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mustang /44-22 Pad
Location ID: 450205



Photo 1. Google Earth aerial imagery taken on June 14, 2016. A disturbance area of 4.53 acres was mapped on 10/12/2017 using a Trimble Juno 3B handheld device (red line). Appears the Operator has overbuilt the location by 1.43 acres (46% overbuilt) per the approved Form 2A .

Inspection Photos
Location Name: Mustang /44-22 Pad
Location ID: 450205



Photo 2. Photo taken from the southern location, facing West. Operator has installed a ditch and berm around the entire location perimeter.



Photo 3. Photo taken from the western location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: Mustang /44-22 Pad
Location ID: 450205



Photo 4. Photo taken from the northern location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the northeastern location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Mustang /44-22 Pad
Location ID: 450205



Photo 6. Photo taken from the eastern location, facing West. Operator has installed an armored ditch.



Photo 7. Photo taken from the previous photo location, facing North. See comments under Photo 6.

Inspection Photos
Location Name: Mustang /44-22 Pad
Location ID: 450205



Photo 8. Photo taken from the entrance of the location, facing South. Operator has installed a cattle guard tracking device.