

# Construction and Stormwater Inspection

October 12, 2017

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC -#8960

Location ID: 450210

Weld County, CO

SWSW Section 26 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Mustang /14-26 Pad  
Location ID: 450210



**Photo 1.** Google Earth aerial imagery taken on June 14, 2016. A disturbance area of 4.33 acres was mapped on 10/12/2017 using a Trimble Juno 3B handheld device (red line). Appears the Operator has overbuilt the location by 1.23 acres (40% overbuilt) per the approved Form 2A .

Inspection Photos  
Location Name: Mustang /14-26 Pad  
Location ID: 450210



**Photo 2.** Photo taken from the western location, facing North. Operator has installed a ditch and berm around the entire location perimeter. Portions of the berm BMP have not been properly compacted and have been left unconsolidated.



**Photo 3.** Photo taken from the northern location, facing East. See comments under Photo 2.

Inspection Photos  
Location Name: Mustang /14-26 Pad  
Location ID: 450210



**Photo 4.** Photo taken from the eastern location, facing South. See comments under Photo 2.



**Photo 5.** Photo taken from the southern location, facing West. See comments under Photo 2.