

Inspection Photos

Location Name: Hoshiko B 35-23

API #: 05-123-21706

Location ID: 332009



Wellhead looking north



Stained soil around wellhead needs to be cleaned up

Inspection Photos

Location Name: Hoshiko B 35-23

API #: 05-123-21706

Location ID: 332009



Battery looking west



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources