

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/21/2017

Submitted Date:

10/13/2017

Document Number:

680102302**FIELD INSPECTION FORM**

Loc ID 335865	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED																																																							
2A Doc Num: _____			Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																							
Operator Information: OGCC Operator Number: <u>10091</u> Name of Operator: <u>BERRY PETROLEUM COMPANY LLC</u> Address: <u>5201 TRUXTUN AVENUE #100</u> City: <u>BAKERSFIELD</u> State: <u>CA</u> Zip: <u>90339</u>																																																										
Contact Information: <table border="1" style="width:100%"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>White, Brent</td> <td></td> <td>BWhite@bry.com</td> <td></td> </tr> <tr> <td>Armstrong, Jon</td> <td></td> <td>JArmstrong@bry.com</td> <td></td> </tr> <tr> <td>Johnson, Derek</td> <td></td> <td>DJohnson@bry.com</td> <td></td> </tr> <tr> <td>Hogelin, Tom</td> <td></td> <td>THogelin@bry.com</td> <td></td> </tr> </tbody> </table>				Contact Name	Phone	Email	Comment	White, Brent		BWhite@bry.com		Armstrong, Jon		JArmstrong@bry.com		Johnson, Derek		DJohnson@bry.com		Hogelin, Tom		THogelin@bry.com																																				
Contact Name	Phone	Email		Comment																																																						
White, Brent		BWhite@bry.com																																																								
Armstrong, Jon		JArmstrong@bry.com																																																								
Johnson, Derek		DJohnson@bry.com																																																								
Hogelin, Tom		THogelin@bry.com																																																								
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>287963</td> <td>WELL</td> <td>XX</td> <td>11/15/2013</td> <td>LO</td> <td>045-13093</td> <td>LONG RIDGE 05B M15 595</td> <td>RI</td> </tr> <tr> <td>287964</td> <td>WELL</td> <td>XX</td> <td>11/18/2013</td> <td>LO</td> <td>045-13092</td> <td>LONG RIDGE 12D M15 595</td> <td>RI</td> </tr> <tr> <td>287965</td> <td>WELL</td> <td>XX</td> <td>11/18/2013</td> <td>LO</td> <td>045-13091</td> <td>LONG RIDGE 12A M15 595</td> <td>RI</td> </tr> <tr> <td>287966</td> <td>WELL</td> <td>XX</td> <td>11/18/2013</td> <td>LO</td> <td>045-13090</td> <td>LONG RIDGE 12C M15 595</td> <td>RI</td> </tr> <tr> <td>420216</td> <td>WELL</td> <td>XX</td> <td>11/18/2013</td> <td>LO</td> <td>045-20106</td> <td>LONG RIDGE 12B M15 595</td> <td>RI</td> </tr> <tr> <td>420231</td> <td>WELL</td> <td>XX</td> <td>11/18/2013</td> <td>LO</td> <td>045-20110</td> <td>LONG RIDGE 05C M15 595</td> <td>RI</td> </tr> </tbody> </table>			Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	287963	WELL	XX	11/15/2013	LO	045-13093	LONG RIDGE 05B M15 595	RI	287964	WELL	XX	11/18/2013	LO	045-13092	LONG RIDGE 12D M15 595	RI	287965	WELL	XX	11/18/2013	LO	045-13091	LONG RIDGE 12A M15 595	RI	287966	WELL	XX	11/18/2013	LO	045-13090	LONG RIDGE 12C M15 595	RI	420216	WELL	XX	11/18/2013	LO	045-20106	LONG RIDGE 12B M15 595	RI	420231	WELL	XX	11/18/2013	LO	045-20110	LONG RIDGE 05C M15 595	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																			
287963	WELL	XX	11/15/2013	LO	045-13093	LONG RIDGE 05B M15 595	RI																																																			
287964	WELL	XX	11/18/2013	LO	045-13092	LONG RIDGE 12D M15 595	RI																																																			
287965	WELL	XX	11/18/2013	LO	045-13091	LONG RIDGE 12A M15 595	RI																																																			
287966	WELL	XX	11/18/2013	LO	045-13090	LONG RIDGE 12C M15 595	RI																																																			
420216	WELL	XX	11/18/2013	LO	045-20106	LONG RIDGE 12B M15 595	RI																																																			
420231	WELL	XX	11/18/2013	LO	045-20110	LONG RIDGE 05C M15 595	RI																																																			
General Comment: This is an Abandoned Location Inspection for Six Wells, listed in Related Facilities, above; permits expired 12/29/2015. The One Conductor Set on Site for the XX Wells, noted in previous Insp Doc#680100962, Dated 7/7/16 has been Closed. It does not appear that these AL Wells were drilled on Location with Four Producing Wells; therefore these would be Well Releases on an Active Location. As Permits have not been Abandoned the Wells can not be released at this time. Refer to Reclamation Section.																																																										

Inspected Facilities				
Facility ID: <u>287963</u>	Type: <u>WELL</u>	API Number: <u>045-13093</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>287964</u>	Type: <u>WELL</u>	API Number: <u>045-13092</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>287965</u>	Type: <u>WELL</u>	API Number: <u>045-13091</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>287966</u>	Type: <u>WELL</u>	API Number: <u>045-13090</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>420216</u>	Type: <u>WELL</u>	API Number: <u>045-20106</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>420231</u>	Type: <u>WELL</u>	API Number: <u>045-20110</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: There is NO Evidence of the AL Wells on this Active Location; however as Documents Abandoning Permits are not in Files they can not be Passed for Final Reclamation at this time.

Corrective Action: File Forms to Abandon Permits for each of the Six AL Wells. Date 11/10/2017

Overall Final Reclamation **Fail** Well Release on Active Location ☒ Multi-Well Location ☒

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401429690	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274438
680102303	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274431