

Inspection Photos  
Well Name: Federal 22-8  
Location ID: 322373



**Photo 1. Main road from Baxter Pass Road to location has multiple areas of erosion and sediment migration down gradient of road surface.**



**Photo 2. Road was partially blocked by fallen rocks at time of inspection. .**



Inspection Photos  
Well Name: Federal 22-8  
Location ID: 322373



**Photo 3. Main road from Baxter Pass Road to location has multiple areas of erosion and sediment migration down gradient of road surface**



**Photo 4. Main road from Baxter Pass Road to location has multiple areas of erosion and sediment migration down gradient of road surface**