

Inspection Photos  
Well Name: Federal 16-2  
Location ID: 322384



**Photo 1. Access road to location has multiple areas of erosion and sediment migration down gradient of road surface.**



**Photo 2. Exposed pipeline in roadway.**

Inspection Photos  
Well Name: Federal 16-2  
Location ID: 322384



**Photo 3. Erosion on southwest corner of location.**



**Photo 4. Erosion on southwest corner of location.**