

On October 18, 2017, COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted an environmental field inspection of Lyster Oil Company Inc Location ID: 313035, Land treatment Facility ID: 452632. Brandon Lyster was on Location. Weather was sunny and temperature low 70s. The following is a summary:

Location ID: 313035

- An approximate 30' x 10' x 15' deep excavation was observed along the west side of the tank battery.
- An approximate 50' x 25' x 18" deep, bermed land treatment cell was observed along the north side of the excavation and tank battery.
- An approximate 80' x 30' x 12-24" deep, bermed land treatment cell was observed along the west side of the Location.
- A disk machine was observed on Location.
- Material in both land treatment cells appeared to have been actively worked by disking.