

Inspection Photos
Well Name: Federal 29-5
Location ID: 322398



Photo 1. Main road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface.



Photo 2. Netting on pit has not been maintained.