

Inspection Photos
Well Name: Federal 32-11
Location ID: 323829



Photo 1. Main road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface.



Photo 2. Erosion of location.

Inspection Photos
Well Name: Federal 32-11
Location ID: 323829



Photo 3. Erosion of location.



Photo 4. Erosion of location.