

Construction and Stormwater Inspection

October 20, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 449376

Adams County, CO

SWNW Section 15 T3S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Aspen 3-65 15-14 /2DH
Location ID: 449376



Photo 1. Photo taken from the entrance of location, facing North. Operator constructing approach for the entrance of location. Culvert has been installed in conjunction with gravel.



Photo 2. Photo taken from the entrance of location, facing Northeast. See comments under Photo 1.

Inspection Photos

Location Name: Aspen 3-65 15-14 /2DH

Location ID: 449376



Photo 3. Photo taken from the southern location, facing East. Operator has cut/mowed disturbance area and has installed a temporary BMP (i.e., filtrex wattle) around the entire perimeter of the location.