

Chevron 22D-17
Api# 05-045-147378
Inspection # 689700504



Location photo

Chevron 22D-17
Api# 05-045-147378
Inspection # 689700504



Shut in well.

Chevron 22D-17
Api# 05-045-147378
Inspection # 689700504



Tank removed from berm. 3 – 2" unused flow lines at berm.