

Inspection Photos  
Location Name: Fur F3 Pad  
Location ID: 335021



Photo 1. Incorrect information on tank sign.



Photo 2. No containment around tank.