

Inspection Photos  
Location Name: Northstar API 045-06436  
10/11/2017



Wellhead looking East



Pit looking south



**Meter shed and separator looking SW**



**Pad and pit looking North**





**Fill slope south edge of pad**



**Location looking NW**



**Petro stained soil at outfall into pit**



**Access road looking NE**



**Communications tower looking SE**



**Wellhead**