

Inspection Photos

Location Name: Northstar API 103-08920 10/11/2017



Wellhead looking West



Wellhead looking NE





Meter shed and separator looking North



210 bbl condensate tanks with stained soils looking NW



Access road looking West



Location looking NW