



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing within the outer project disturbance and comprised of species such as western wheatgrass (*Pascopyrum smithii*) and perennial ryegrass (*Lolium perenne*).



Photo 3. View of the eastern portion of the project area from the northeastern corner of the project area facing southward.