

Location

Lease Road:			
	Type	Access	
	comment:	Gravel two track through pasture	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign mounted to meter shed	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input style="width: 95%;" type="text"/>	
	Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	LOCATION	
	Comment:	Wire fence around location. Fence is in disrepair. Remove or repair fence. Pasture is occupied with ranchers cattle	
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 0		
	Comment:	Removed from unit	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	Vertical gas separator in metal shed	
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
	Comment:		
Corrective Action:			Date:
Type: Pump Jack	# 1		
	Comment:	Pump unit stored on location. Horsehead removed	
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
	Comment:	Meter shed on north side of metal shed	
Corrective Action:			Date:

Type: Ancillary equipment	# 0		
Comment:	Gas scrubber disconnected		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 281983 Type: WELL API Number: 125-09754 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: Erosion leading off of location needs to be repaired

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT