

Inspection Photos
Location Name: HORSESHOE CANYON 1-16
Location ID: 312620



Photo 1. Location photo. No plugging operations at time of inspection. Form 42 for start of plugging should be updated.