

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2017

Submitted Date:

10/25/2017

Document Number:

688300523**FIELD INSPECTION FORM**
 Loc ID 450063 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	Production
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	All DJ Basin Inspections
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	Regulatory Supervisor
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All DJ Basin Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450062	WELL	XX	09/29/2017		005-07271	Grande 4-65 20-19 3AH	WO

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action: _____ Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 450062 Type: WELL API Number: 005-07271 Status: XX Insp. Status: WO**BradenHead**Comment: Form 17 to be submitted by operator.

0 min Casing 35 psi, Bradenhead -2" Hg, vacuum for 3 sec
5 min Casing 35 psi, Bradenhead Slight vacuum that died immediately
10 min Casing 35 psi, Bradenhead Slight vacuum that died immediately
15 min Casing 35 psi, Bradenhead Dead
20 min Casing 35 psi, Bradenhead Slight vacuum that died immediately
25 min Casing 35 psi, Bradenhead Dead
30 min Casing 35 psi, Bradenhead Dead

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300534	Conoco Grand 4-65 20-19 3AH Bradenhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4284245