

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Well heads

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Location photo

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Open gap in netting.

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Hole in netting.

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Hole in netting.

AP 22-10-695
Api# 05-045-12507
Inspection # 689700519



Hyd