

Inspection Photos

10/25/2017

Operator: DAVIS OIL COMPANY - 22900

Location ID: 375811

Inspection Doc. Number: 682502749

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: DAVIS OIL COMPANY - 22900
Location ID: 375811



Photo 1: Photo taken from the well location. Previous inspection (#682500903) required operator to remove concrete debris from the location. Photo shows concrete debris has not been removed.



Photo 2: Photo taken from the east of the well. Photo shows concrete debris remaining.