

Inspection Photos

10/25/2017

Operator: PETROLEUM INC - 69450

Location ID: 375181

Inspection Doc. Number: 682502753

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETROLEUM INC - 69450
Location ID: 375181



Photo 1: Photo taken from the well location, facing southeast. Photo shows overview of the location, areas where vegetation has failed to re-establish, and equipment that has not been removed per corrective actions.



Photo 2: Photo taken from the west end of the location, facing east. Photo shows areas where vegetation has failed to re-establish, and equipment that has not been removed per corrective actions.

Inspection Photos
Operator: PETROLEUM INC - 69450
Location ID: 375181



Photo 3: Photo taken from the south end of the location. Photo shows equipment remaining on location.



Photo 4: Photo taken from the east end of the location. Photo shows equipment remaining on location.