

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2017

Submitted Date:

10/25/2017

Document Number:

671000591

FIELD INSPECTION FORM

Loc ID 308038 Inspector Name: DURAN, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Findings:**5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Fitzgerald, Edie	719-845-2108/719-859-1394	ediefitzgerald@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260403	WELL	PR	07/22/2010	GW	071-07425	HILL RANCH 03-15V	PR
260437	WELL	AL	04/08/2003	LO	071-07429	HILL RANCH 03-15R	AL

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Deadman # & Marked	# 5				
Comment:					
Corrective Action:		Date:			
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:		Date:			
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 260403 Type: WELL API Number: 071-07425 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 260437 Type: WELL API Number: 071-07429 Status: AL Insp. Status: AL

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: 30' x 80'

Corrective Action

Date:

Monitoring:	Monitoring Type	Comment
	Chain	yellow