



Photo 1. View from the northwestern corner of the project area facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation within the interim reclamation area is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and brome grass (*Bromus* sp.).



Photo 3. View of the southern portion of the project area from the southwestern edge facing eastward.



Photo 4. View of pipe segments southwest of the project area.





Photo 5. Another view of pipe segment southwest of the project area.