

Photo#1:
Overview of Location from Entry into Location to East.



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe McIntyre Loc#312997

Photo#2:

Photo#3:

Noxious Weeds, Scotch & Canada thistle are established on Cut Slopes.



October 21, 2017





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe McIntyre Loc#312997

Photo#4:

Noxious Weeds, Scotch & Canada Thistle are established along Access Road & adjacent Range Land.

Photo#5:



October 21, 2017

Photo#6:

Photo#7:

Unused Equipment and Supplies stored on Location



October 21, 2017

Photo#8:

Unused Equipment and Supplies stored on Location

Photo#9:



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe McIntyre Loc#312997

Photo#10:

Various Debris is scattered across Location



October 21, 2017

Photo#11:



Photo#12:

Photo#13:

Equipment Debris on Location




October 21, 2017

Photo#14:

Photo#15:

Rill Erosion on Cut Slopes



October 21, 2017

Photo#16:

Views of Wellhead ; It does not appear CAs from Previous Inspections have been resolved

Photo#17:



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe McIntyre Loc#312997