



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Aug 23, 2017 12:51:00 PM MDT
Server Receive Date:	Aug 23, 2017 5:09:40 PM MDT
Reference Number:	20170823-1865176495
Location:	500 Forest Srvs Rd, Bayfield, CO 81122, USA Aug 23, 2017 12:47:56 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Aug 23, 2017
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	Northeast
Well Name	ARCHULETA-DIX GAS UNIT 1
API Number	50670703800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

Filled in erosion channel then placed rock bmp to stop future erosion. Pulled 10 musk thistle rosetts.