

Construction and Stormwater Inspection

October 25, 2017

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 440396

Weld County, CO

NENE Section 35 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 1. Photo taken from the entrance of location, facing West. Vehicle tracing devices installed.



Photo 2. Photo taken from the entrance of location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 3. Photo taken from the southeast location, facing North. Ditch and berm BMP installed around the perimeter of the location. Appears hydromulch has been applied to the ditch and berm BMP to temporarily stabilize BMP.



Photo 4. Photo taken from the northwest location, facing East. See comments under Photo 3. Topsoil salvaged and stored along the northern perimeter.

Inspection Photos
Location Name: Hergert /35-D Pad
Location ID: 440396



Photo 5. Photo taken from the northwest location, facing South. See comments under Photo 3.



Photo 6. Photo taken from the southwest location, facing Southeast. Retention area constructed along the southwestern location with a stabilized outlet device.