

Inspection Photos
Location Name: UPRR 42 Pan Am AJ #1
API: 05-123-09130



Photo 1: Wellhead, looking N

Photo 2: Weeds along lease road, looking S



Inspection Photos
Location Name: UPRR 42 Pan Am AJ #1
API: 05-123-09130



Photo from prior inspection for comparison



Photo 3: Bradenhead plumbed to surface, stained soil removed