

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2017

Submitted Date:

10/30/2017

Document Number:

685100261

FIELD INSPECTION FORM

Loc ID 324612 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dodek, Brian	720-225-6653	BDodek@bonanzacrk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212140	WELL	PR	11/18/2007	OW	057-06033	MCCALLUM UNIT 52	EI
452755	SPILL OR RELEASE	AC			-	McCallum Unit 52	EI

General Comment:

Environmental Staff, Kris Neidel inspected the McCallum #52 and spill number 401441291 on 10/26/2017. The weather was dry and overcast 40 degrees. The spill had been stopped and visual contaminated soils have been stockpiled on the well pad. There appeared to be approximately 2 yards of soil. Visual contaminated soil that left the pad had been collected. Bonanza has reported on the Form 19 that they will be collecting soil samples to demonstrate compliance with COGCC table 910-1. Photos Attached.

Inspected Facilities

Facility ID: 212140 Type: WELL API Number: 057-06033 Status: PR Insp. Status: EI

Facility ID: 452755 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100262	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4287928