

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2017

Submitted Date:

10/31/2017

Document Number:

674200315

**FIELD INSPECTION FORM**

Loc ID 335664 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250886	WELL	PR	09/24/1997	GW	123-18689	VESSELS MINERALS 'E' 1	PA
278108	WELL	PR	05/24/2006	GW	123-23018	VESSELS 24-19	PA
278119	WELL	PR	05/24/2006	GW	123-23009	VESSELS 23-19	PA
411850	WELL	PR	07/26/2009	GW	123-30276	VESSELS MINERALS 13-19	PA
411852	WELL	PR	07/28/2009	GW	123-30277	VESSELS MINERALS 4-6-19	PA
411854	WELL	PR	07/30/2009	GW	123-30278	VESSELS MINERALS 2-4-19	PA
411855	WELL	PR	07/26/2009	GW	123-30279	VESSELS MINERALS 14-19	PA

**General Comment:**

**Inspected Facilities**

Facility ID: 250886 Type: WELL API Number: 123-18689 Status: PR Insp. Status: PA

Facility ID: 278108 Type: WELL API Number: 123-23018 Status: PR Insp. Status: PA

Facility ID: 278119 Type: WELL API Number: 123-23009 Status: PR Insp. Status: PA

Facility ID: 411850 Type: WELL API Number: 123-30276 Status: PR Insp. Status: PA

Facility ID: 411852 Type: WELL API Number: 123-30277 Status: PR Insp. Status: PA

Facility ID: 411854 Type: WELL API Number: 123-30278 Status: PR Insp. Status: PA

Facility ID: 411855 Type: WELL API Number: 123-30279 Status: PR Insp. Status: PA

**Workover**

Comment: RIH 2 drill collars to tag cement top at 305' (KB). PU Swabbco swivel and established circulation. Continued to drill out 8-5/8" internal plug from 305' to 540' KB (18 Total Collars in Hole). Rolled hole clean. RD Swivel. PO/LD 6 drill collars - Stood back 6 stands. SWI. Secure

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT