

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2017

Submitted Date:

10/31/2017

Document Number:

674200316**FIELD INSPECTION FORM**

Loc ID 335664 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250886	WELL	PR	09/24/1997	GW	123-18689	VESSELS MINERALS 'E' 1	PA
278108	WELL	PR	05/24/2006	GW	123-23018	VESSELS 24-19	PA
278119	WELL	PR	05/24/2006	GW	123-23009	VESSELS 23-19	PA
411850	WELL	PR	07/26/2009	GW	123-30276	VESSELS MINERALS 13-19	PA
411852	WELL	PR	07/28/2009	GW	123-30277	VESSELS MINERALS 4-6-19	PA
411854	WELL	PR	07/30/2009	GW	123-30278	VESSELS MINERALS 2-4-19	PA
411855	WELL	PR	07/26/2009	GW	123-30279	VESSELS MINERALS 14-19	PA

General Comment:

Inspected Facilities

Facility ID: <u>250886</u>	Type: <u>WELL</u>	API Number: <u>123-18689</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>278108</u>	Type: <u>WELL</u>	API Number: <u>123-23018</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>278119</u>	Type: <u>WELL</u>	API Number: <u>123-23009</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>411850</u>	Type: <u>WELL</u>	API Number: <u>123-30276</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>411852</u>	Type: <u>WELL</u>	API Number: <u>123-30277</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>411854</u>	Type: <u>WELL</u>	API Number: <u>123-30278</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>411855</u>	Type: <u>WELL</u>	API Number: <u>123-30279</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>

Workover

Comment: All personnel did final walk arounds prior to starting their tasks. IPSI'S 134 (blew down instantly). Pu/Mu STS BHA 7-7/8" Cone Bit and XO's. RIH 4 drill collars to tag cement top at 125' (KB). PU Swabbco swivel and established circulation. Continued to drill out 8-5/8" internal plug from 125' to 235' KB. Rolled hole clean. RD Swivel and swapped out pumps. PO/LD 2 drill collars and stood back 3 stands of 3-1/8" DC with BHA

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
			Pass	Vehicle Tracking		
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT