

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2017

Submitted Date:

10/31/2017

Document Number:

679903356**FIELD INSPECTION FORM**

Loc ID 324785 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10017Name of Operator: CHACO ENERGY COMPANYAddress: P O BOX 1587City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|---------------|------------------|------------------------------------|
| Nelson, Alan | (405)942-3751 | chaco@swbell.net | Production Manager |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212573 | WELL | PR | 07/01/2003 | GW | 061-05024 | STATE 1-16 | PR |

General Comment:

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Lease sign mounted to fence at tank battery | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sticker and stencil on tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------------------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Wire fence around tank | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Metal panels around HGS | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter shed on north side of HHS | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|--|-------|
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | HHS on west side of tank | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 0 | |
| Comment: | Plunger lift removed to free flow through tubing | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|----------------|-----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | <100 BBLs | STEEL AST | | 38.319350,-102.795520 |
| Comment: | 90bbl oil tank | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 212573 | Type: | WELL | API Number: | 061-05024 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Location and access are grassed over. Access has deep tracks and needs to be maintained

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT