

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401390880

Receive Date:

09/06/2017

Report taken by:

CHRIS CANFIELD

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

|  |  |                              |
|--|--|------------------------------|
| Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u> | Operator No: <u>47120</u>              | <b>Phone Numbers</b>         |
| Address: <u>P O BOX 173779</u>                               |  | Phone: <u>(970) 336-3500</u> |
| City: <u>DENVER</u>  | State: <u>CO</u>                       | Zip: <u>80217-3779</u>       |
| Contact Person: <u>Phil Hamlin</u>                           | Email: <u>Phil.Hamlin@anadarko.com</u> | Mobile: <u>( )</u>           |

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 4891 Initial Form 27 Document #: 1632378

#### PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water        |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                             | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                 | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                                  |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____   |

#### SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

|   |                            |   |                               |
|---|----------------------------|---|-------------------------------|
| Facility Type: <u>LOCATION</u>                | Facility ID: <u>320405</u> | API #: _____  | County Name: <u>ADAMS</u>     |
| Facility Name: <u>HSR-DREYER-61S65W 5SWNW</u> |                            | Latitude: <u>39.996994</u>                                | Longitude: <u>-104.693622</u> |
|   |                            | ** correct Lat/Long if needed: Latitude: <u>39.996825</u> | Longitude: <u>-104.693891</u> |
| QtrQtr: <u>SWNW</u>                           | Sec: <u>5</u>              | Twp: <u>1S</u>  | Range: <u>65W</u>             |
|   |                            | Meridian: <u>6</u>  | Sensitive Area? <u>Yes</u>    |

#### SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Residential

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

#### Other Potential Receptors within 1/4 mile

Surface water approximately 700 feet (ft) west, water well approximately 400 ft south, building approximately 440 ft southwest, and groundwater approximately 8 ft below ground surface (bgs).

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

| Impacted? | Impacted Media | Extent of Impact               | How Determined                   |
|-----------|----------------|--------------------------------|----------------------------------|
| Yes       | GROUNDWATER    | See attached data              | Groundwater Samples/Lab Analysis |
| Yes       | SOILS          | 25ft N-S X 25ft E-W X 10ft bgs | Soil Samples/Lab Analysis        |

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The water sump at the HSR-Dreyer 5-5 tank battery floated following a heavy rain event. The water sump was removed and it was discovered that the threads were partially stripped, releasing an unknown volume of oil and produced water. The well was shut in and the petroleum hydrocarbon impacted soil was excavated. Groundwater was encountered in the excavation at approximately 9 ft bgs.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Please refer to the Form 27 submitted to the Colorado Oil and Gas Conservation Commission (COGCC) on January 27, 2010.

#### Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater monitoring has been conducted on a quarterly basis since December 2009.

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 13

Number of soil samples exceeding 910-1 5

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 625

### NA / ND

-- Highest concentration of TPH (mg/kg) 5130

NA Highest concentration of SAR

BTEX > 910-1 Yes

Vertical Extent > 910-1 (in feet) 9

### Groundwater

Number of groundwater samples collected 704

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 8'

Number of groundwater monitoring wells installed 31

Number of groundwater samples exceeding 910-1 252

-- Highest concentration of Benzene (µg/l) 48000

-- Highest concentration of Toluene (µg/l) 68000

-- Highest concentration of Ethylbenzene (µg/l) 1700

-- Highest concentration of Xylene (µg/l) 44000

NA Highest concentration of Methane (mg/l)

### Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Based on the surveyed groundwater flow direction to the northwest, additional point of compliance (POC) monitoring wells will be installed.

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please refer to the Form 27 submitted to the COGCC on January 27, 2010.

## REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the Form 27 submitted to the COGCC on January 27, 2010. Between June 2013 and October 2014, monitoring wells MW01, MW07, MW09, MW10, MW16, MW19, and MW20 were purged of free product once every two weeks using a disposable bailer. Purging was discontinued after the October 2014 event due to lack of measurable product. A total of approximately 368 gallons of free product mixed with groundwater were purged from the wells and transferred to a nearby Kerr-McGee produced water sump. The quarterly depth to water and depth to product measurements are summarized in Table 1.

Due to persistent, elevated benzene concentrations in multiple site monitoring wells, additional remedial options are under evaluation.

## Soil Remediation Summary

☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

☒ Ex Situ

Yes \_\_\_\_\_ Excavate and offsite disposal  
If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 230  
Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
No \_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

Yes \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
No \_\_\_\_\_ Chemical oxidation  
No \_\_\_\_\_ Air sparge / Soil vapor extraction  
Yes \_\_\_\_\_ Natural Attenuation  
Yes \_\_\_\_\_ Other \_\_\_\_\_ Groundwater Removal \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater monitoring wells MW01 through MW28 are sampled on a quarterly basis and submitted for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX) by United States Environmental Protection Agency (USEPA) Method 8260C. Groundwater monitoring will continue on a quarterly basis. The monitoring well locations are depicted on Figure 1. The Groundwater Elevation Contour Map generated using the June 2017 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical report for the June 2017 groundwater monitoring event is attached.

Based on the surveyed groundwater flow direction to the northwest, additional POC monitoring wells will be installed. Groundwater monitoring will continue on a quarterly basis until a No Further Action status request is warranted.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☐ Quarterly ☐ Semi-Annually ☒ Annually ☐ Other \_\_\_\_\_

**Report Type:** ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report  
☐ Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards 230

E&P waste (solid) description Petroleum hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: Buffalo Ridge Landfill in Keenesburg, Colorado

Volume of E&P Waste (liquid) in barrels 58

E&P waste (liquid) description Petroleum hydrocarbon impacted groundwater (49 barrels from excavation; 9 barrels bailed from MWs)

COGCC Disposal Facility ID #, if applicable: 159443

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDATION COMPLETION REPORT

### REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No \_\_\_\_\_

Do all soils meet Table 910-1 standards? Yes \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? No \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? No \_\_\_\_\_

Is additional groundwater monitoring to be conducted? Yes \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The Kerr-McGee facility was decommissioned. The site was restored to its pre-release grade.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. 09/18/2009

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/18/2009

Date of commencement of Site Investigation. 09/18/2009

Date of completion of Site Investigation. \_\_\_\_\_

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 09/18/2009

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

|  |
|--|
|  |
|--|

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin

Title: Senior HSE Representative

Submit Date: 09/06/2017

Email: Phil.Hamlin@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CHRIS CANFIELD

Date: 10/31/2017

Remediation Project Number: 4891

### COA Type

### Description

|  |  |
|--|--|
|  |  |
|--|--|

## **Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

|           |                                |
|-----------|--------------------------------|
| 401390880 | FORM 27-SUPPLEMENTAL-SUBMITTED |
| 401391024 | LOGS                           |
| 401392027 | ANALYTICAL RESULTS             |
| 401395420 | SITE MAP                       |
| 401395421 | GROUND WATER ELEVATION MAP     |

Total Attach: 5 Files

## **General Comments**

### User Group

### Comment

### Comment Date

|  |  |                     |
|--|--|---------------------|
|  |  | Stamp Upon Approval |
|--|--|---------------------|

Total: 0 comment(s)