

Inspection Photos

Location Name: HSR-Hunter 9-32

API #: 05-123-19518

Location ID: 330727



Wellhead looking northwest



Stained soil around wellhead needs to be cleaned up



Inspection Photos

Location Name: HSR-Hunter 9-32

API #: 05-123-19518

Location ID: 330727



Battery looking north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources