

Photo#1:
Location 10/4/17



Photo#2:
Location 10/25/17



October 25, 2017

Photo#3:

10/4/17

Wattles dislodged by Livestock have been newly installed;

Photo#4:

10/25/17



October 25, 2017

Photo#5:

Noxious Weeds have been Controlled.

10/4/17



Photo#6:

10/25/17



October 25, 2017

Photo#7:

10/4/17



October 25, 2017

Perimeter Controls have been installed on East Side.

Photo#8:

10/25/17



Photo#9:

New Wattles have been installed, but are not properly seated in.



October 25, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Hebron Marr Loc#413754