

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2017

Submitted Date:

11/01/2017

Document Number:

671000649**FIELD INSPECTION FORM**Loc ID 333913 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-845-2108/719-859-1394	ediefitzgerald@tcenergy.us	All Inspections
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258761	WELL	PR	02/22/2001	GW	071-07148	HILL RANCH 04-15V	PR
258965	WELL	PR	02/06/2003	GW	071-07174	HILL RANCH 04-15R	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258761	Type:	WELL	API Number:	071-07148	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	258965	Type:	WELL	API Number:	071-07174	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 40' x 70', sharedCorrective Action: Date: Monitoring: Monitoring Type: Comment: Other:

Blue stake