



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*), rubber rabbitbrush (*Chrysothamnus nauseosus*) and dropseed (*Sporobolus* sp.).



Photo 3: View of the western portion of the project area from the southwestern corner facing northward.



Photo 4: View of cobble run down in the southeastern portion of the project area appears to be functioning at this time.