

## Inspection Photos

Location Name: Zeiler 16-7

API #: 05-123-23817

Location ID: 332943



**Zeiler 16-7 wellhead looking west. Well is TA**



**Unused methanol tank and fencing has been removed from Zeiler 15-7 wellhead**



**Inspection Photos**  
**Location Name: Zeiler 16-7**  
**API #: 05-123-23817**  
**Location ID: 332943**



**Wellheads looking west**

