


Inspection Photos

Location Name: Bernhardt 4-36

API #: 05-123-15488

Location ID: 328058



Wellhead looking west



Stained soil under master valve has been cleaned up

