

Inspection Photos
Location Name: Zimmerman/Chamberlin 1
API: 05-081-06668



Photo 1. View of location facing west.



Photo 2. View of battery facing southeast.

Inspection Photos
Location Name: Zimmerman/Chamberlin 1
API: 05-081-06668



Photo 3. Run-on occurring on southeast side of location.



Photo 4. 2 – 1" steel risers not LO/TO.

Inspection Photos
Location Name: Zimmerman/Chamberlin 1
API: 05-081-06668



Photo 5. Equipment stored on location.



Photo 6. 2 – 1" steel risers not LO/TO.