

- Ranger Federal 24 - 7
- 05-033-06064



Photo 1: Wellhead sign previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 2: Wellhead sign follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 3: Tank with not capacity label previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 4: Tank labeled follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 5: Pipe section behind open top tank previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 6: Pipe section removed follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 7: Impacted soil below tank valve previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 8: Cleaned up impacted soil follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 9: Impacted soil at wellhead previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 10: Removed impacted soil at wellhead follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 11: Unused equipment previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 12: Removed unused equipment follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 13: Unused risers and pipe at tanks previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 14: Removed risers and pipe follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 15: Unused risers previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 16: Risers removed follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 17: Unused risers previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 18: Removed risers follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 19: Unused risers previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 20: Removed risers follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 21: Unused riser previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 22: Removed riser follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 23: Unused riser previous inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 24: Removed riser follow-up inspection.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 25: Location overview from back of location.

- Ranger Federal 24 - 7
- 05-033-06064



Photo 26: Location overview from entrance.