

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 1: Wellhead sign. Previous inspection.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 2: Wellhead sign. Follow-up inspection.



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 3: Disconnected wellhead and riser. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 4: Wellhead. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 5: Unused risers on the N side of location W of meter run house. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 6: Removed risers. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 7: Unused risers on the E side of meter run house. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 8: Removed risers. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 9: Unused riser and abandoned flowline at meter run. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 10: Removed riser and flowline at meter run. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 11: Unused riser at wellhead. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 12: Removed riser at wellhead. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 13: Unused riser S side of separator. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 14: Removed risers. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 15: Unused risers marked with painted rocks and deadman in left of frame. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 16: Removed risers and marked anchor. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 17: Thistle going to seed along S perimeter. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 18: Cleaned up S perimeter area. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 19: Thistle going to seed out from tank battery. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 20: Cleaned up area with Thistle removed. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 21: Unused risers inside tank berms. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 22: Removed risers. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 23: Impacted soil and gravel under valve. One of several that need to be cleaned up. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 24: Cleaned up impacted soil. Follow-up inspection.**



- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 25: Graveled area with partial berms in NW corner of location. Previous inspection.**

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



**Photo 26: Cleaned up area with berms knocked down. Follow-up inspection.**