



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), dropseed (*Sporobolus* sp.), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of the western portion of the project area from the southwestern edge of the working area facing northward.