

Inspection Photos
Location Name: Cow Skull 1
Location ID: 414132



Photo 1. Location Photo.



Photo 2. No capacity listed on Produced water tanks.

Inspection Photos
Location Name: Cow Skull 11-98-18
Location ID: 414132



Photo 3. No capacity listed on Produced water tanks.



Photo 4. Stored Equipment near pump jack. No labels on chemical container. Areas of stained soils.

Inspection Photos
Location Name: Cow Skull 11-98-18
Location ID: 414132



Photo 5. Frack tank labeled as Produced Water with lines running to API 051-06100 but disconnected at time of inspection.



Photo 6. Disconnected lines at wellhead.

Inspection Photos
Location Name: Cow Skull 11-98-18
Location ID: 414132



Photo 7. Pipe, pallets and sawdust debris/trash on location.



Photo 8. Pump jack parts stored on location.