

Inspection Photos
Location Name: Hughes 11-90-26 2
Location ID: 428191



Photo 1. Hatches open on unused tanks.



Photo 2. Incorrect signage on unused tanks.

Inspection Photos
Location Name: Hughes 11-90-26 2
Location ID: 428191



Photo 3. Wellhead has been disconnected from production.



Photo 2. Unused tanks.